

ANNEXURE - B

FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Assistant Engineer
Stella Man's E.M School,
Valayavattom, Thiruvallur
RCC Building

Building 1 - 49.25 x 6 x 3.65m UF
- 49.25 x 6 x 3.70m FF
- 49.25 x 6 x 3.75m SF

Building 2 - 32.30 x 6.15 x 3.60m GF
- 45.90 x 6.20 x 3.60m
- 19.65 x 6.20 x 3.60m
- 6.10 x 6.65 x 3.55m
- 32.30 x 6.15 x 3.65m S

5. Period for which the certificate is issued 2026-27

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)

Nil

7. Any major defects noticed which will render the building unsafe in any manner

Nil

8. Whether maintenance works have been done properly

Yes

9. Whether the structure is sound or not for conducting classes

Yes, Sound under normal weather and climate and his

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Item No. 9 in Annexure-A, Safety shall ensure as per letter No. GEDN-M1/188/2025 dt. 25/5/26.

CERTIFICATE

certified that the school building was inspected by me on 30/05/2026 and found to be fit / unfit to conduct classes, for the period 2026-27 for the reasons stated above.

Place: Kadapra

Date: 30/5/2026



Assistant Engineer
ASSISTANT ENGINEER
LID & EW SECTION
KADAPRA

Annexure ARevised Checklist for School FitnessSchool Name: STELLA MARIS E.M. SCHOOL, VALANJAVATTOM.School Code : 930713School Type (Govt./Aided/Unaided): Unaided.

Sl.No.	Item to be verified	Yes	No	Remarks
1.	Building Structurally stable	☒	☐	
2.	Existing compound walls safe and intact	☒	☐	
3.	Premises free of unsafe pits, mounds and slopes.	☒	☐	
4.	Whether the new Constructions comply with Building Rules & approvals	☐	☐	NA
5.	Dangerous/ overgrown trees and branches pruned or removed	☒	☐	
6.	Kitchen does not have any safety issue	☐	☐	No Kitchen in the school
7.	Whether Asbestos/Tin/ Aluminium sheet roofs have been replaced?	☐	☐	NA
8.	Whether Parapet Walls are there for wells and open wells are covered ?	☒	☐	
9.	Electrical wiring safe (old/damaged wiring replaced)	☐	☐	

Safety shall ensure as per letter no. GEDW-M1/188/25
 A. Edn of Principal
 Secretary dt. 25/5/26

10. Transformers (if nearby) fenced properly ☐ ☐ NA
11. No exposed or hazardous electric posts/ electric wires near school. ☒ ☐
12. Fire extinguisher installed ☒ ☐

The inspecting officer may offer remarks regarding item 10 and 11. The head of institution shall rectify the defects and obtain NOC from KSEB in cases pertaining to Items 10 and 11.

HEALTH AND SANITATION

13. Adequate, clean, ventilated toilets with running water ☒ ☐
14. Classrooms, common areas and kitchen are clean ☒ ☐
15. First aid kit available ☒ ☐
16. Overgrown vegetation/garbage removed from School premises ☒ ☐
17. Rodent control measures are in place ☒ ☐

Items 13 to 17 are to be certified by the Health staff (HI/HS) of the concerned Local Body.

Signature & Seal of School Principal/HM: Govindarajan **PRINCIPAL**
STELLA MARIS E.M. SCHOOL
VALANJAVATTOM P.O.
THIRUVALLA - 4

Signature & Seal of Health inspector :

Signature & Seal of Assistant Engineer, LSGD:

Inspection Date: 30/5/2026

ASSISTANT ENGINEER
LID & EW SECTION
KADAPRA

HEALTH INSPECTOR
PHC KADAPRA