

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Assistant Engineer
Stella Maris EM School Valanjavattom

RCC Building

Building-1 - 49.25x6x3.65m G.F
- 49.25x6x3.70m F.F
- 49.25x6x3.75m S.F

Building-2 - 32.30x6.15x3.60m G.F
2025-26 - 45.90x6.20x3.60m

5. Period for which the certificate is issued

6. Nature of defects , if any

a) Foundation and basement

b) Superstructure

c) Doors and Windows

d) Wood work wrought and put up

e) Roof

f) Flooring

g) Miscellaneous (Cracks, etc.)

7. Any major defects noticed which will render the building unsafe in any manner

8. Whether maintenance works have been done properly

9. Whether the structure is sound or not for conducting classes

- 19.65x6.20x3.60m

- 6.10x6.65x3.5m

- 32.30x6.15x3.55m F.F

Nil

- 45.90x6.20x3.55m

- 19.65x6.20x3.55m

- 6.10x6.65x3.55m

- 32.30x6.15x3.65m S.F

Nil

- 45.90x6.20x3.65m

- 19.65x6.20x3.65m

Yes

- 6.10x6.65x3.65m

Yes sound under normal weather and climate conditions.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

certified that the school building was inspected by me on 27/05/2025 and

found to be fit / unfit to conduct classes, for the period 2025-26 for the reasons stated above.

Place: Kadappa

Date: 27/05/2025



Assistant Engineer
ASSISTANT ENGINEER
LID & EW SECTION
KADAPPA